

SECRET25X1
25X1

O -18-200518-08

This document contains
3 pages.

Copy 8 of 9 copies

29 February 1968

EVALUATION SUMMARYMission BX-6851

1. Processing and Titling - Field
2. Physical Condition - Good
3. Hypo Retention Rewashing required (Patch 3, HT-2 test)
4. Exposure (based on density) - Medium
5. General Comments:
 - A. Total mission contained 14 parts.
 - B. Part 8 required dual printing.
 - C. Dye retention was prevalent throughout the mission. It was reprocessed to remove excess dye.
 - D. Estimated cloud cover and/or water is 75%. 7 parts were 100% clouds and/or water.
 - E. Small emulsion skip type defect on Part 13, Frames 971-974. (Pictures recorded)
 - F. A few frames show evidence of erratic film tracking (camera); example: Part 9, Frames 609-628, Part 14, Frames 1038-1040.
 - G. Part 6, Frame 397 contained an ultrasonic splice. The splice apparently was not taped (reinforced) at presplice.
 - H. A few frames contain the clock in the format.
 - I. A small amount of pinholes was observed intermittently throughout the mission.
 - J. The first and last frames of most parts show evidence of handling marks. These are attributed to inserting grids and replacing idents in house.

SECRET

25X1

25x1

MISSION NO. BX-6851 EVALUATION REPORT

Evaluated By Q.C. Technicians

Camera Fwd/Aft

Evaluation Date 22 February 1968

Emulsion 3404

Film Tracking Good

Clock Exposure

Data Chamber (image quality) Good

Apparent Resolution Normal

Density Medium

Contract No. 1

EDUCATIONALS.

<u>Part</u>	<u>Frames</u>	<u>Comments</u>
1	1-76 2-12	Intermittent edge wrinkle Fog
2		
3		
4		
5	378 380	HT-2 test spot Cinch mark
6	405 406	Cinch mark Ultrasonic splice
7	457-532	Emulsion scratch
8	533-608	Intermittent emulsion scratch
9		
10	685-752 685,688 686 748 741-751	Intermittent emulsion scratch Embedded dirt, abrasions, splice Abrasions HT-2 test spot Fog

~~SECRET~~

SECRET

25X1

Discrepancies (Cont'd) Camera

<u>Part</u>	<u>Frames</u>	<u>Comments</u>
10	685-760	Intermittent emulsion scratch
11	761-836	Emulsion scratch
12	837-912	Intermittent emulsion scratch
13	913-988 971-974	Emulsion scratch Emulsion defect
14	989-1046 990	Emulsion scratch HT-2 test spot

SECRET

25X1